

Metal Earth.

3D METAL MODEL KITS




Japanese Rickshaw
Item No. MMS120



It is highly recommended that you visit www.metalearth.com/360/mms120 to see the completed model before assembling your own

Assembly Flow Chart



Legends:


- E** Engraved side
- NE** Non-engraved side
- Attention point
- Insert tab and bend 90 degrees
- Insert tab and twist 90 degrees

Recommended tools:

-Wire cutters: helpful for taking parts from the metal sheets.




-Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.




Assembly tip:

If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish



Metal sheets



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

