
3D METAL MODEL KITS




Dr. W ho Ta rd is Item No. MM\$400M





It is highly recommended that you visit www.metalearth.com/360/mms400m to see the completed model before assembling your own



Legends:



Engraved side



Non-engraved side





Attention point



Insert tab and bend 90 degrees



0

Insert tab and twist 90 degrees

If needed, slightly twist tabs to hold parts together then untwist and bend them down for a nice finish

Recommended tools:


-Wire cutters: helpful for taking parts from the metal sheets.



-Tweezers or needle nose pliers: helpful for folding parts, bending and twisting tabs.









1

In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

